DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES (X1) PROVIDER/SURPLIER/CLIA

	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	A. BUIL	ULTIPLE CONSTRUCTION _DING	(X3) DATE SU COMPLE	
		145662	B. WIN	G		C 3/2005
	ROVIDER OR SUPPLIER	ENTRE		STREET ADDRESS, CITY, STATE, ZIP CO 8333 WEST GOLF ROAD NILES, IL 60714	•	0/2000
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG		IOULD BE CROSS-	(X5) COMPLETION DATE
F9999	a) The advisory phy committee shall develope to be followed during emergencies that man long-term care facilal emergencies include things as: 3) Traumatic in burns, and laceration	E FINDINGS: Medical Emergencies visician or medical advisory velop policies and procedures og the various medical may occur from time to time in ities. These medical le, but are not limited to, such juries (for example, fractures, ons). General Requirements for	F99	999		

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES (X1) PROVIDER/SUBBLIED/CLIA

	TEMENT OF DEFICIENCIES OPLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) M A. BUI		IPLE CONSTRUCTION IG	(X3) DATE SURVEY COMPLETED	
		145662	B. WIN	NG _			3/ 2005
	ROVIDER OR SUPPLIER	ENTRE		8	REET ADDRESS, CITY, STATE, ZIP CODE 333 WEST GOLF ROAD WILES, IL 60714	00/20	3,2000
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOULD I REFERENCED TO THE APPROPRIATE D	BE CROSS-	(X5) COMPLETION DATE
F9999	a) The facility must and services to atta practicable physica well-being of the reeach resident's complan of care. Adequating care and pet to each resident to personal care need b) General nursing minimum the follow a 24-hour, seven da 6) All necessary assure that the resident resident nursing personnel state each resident reand assistance to permitted only in control of these REGULATION by: Based on observatifacility 3-8-05 staffing policies, facility and	provide the necessary care ain or maintain the highest I, mental, and psychological sident, in accordance with aprehensive assessment and late and properly supervised ersonal care shall be provided meet the total nursing and is of the resident. I care shall include at a ring and shall be practiced on ay a week basis: I y precautions shall be taken to dents' environment remains hazards as possible. All shall evaluate residents to see receives adequate supervision prevent accidents. Codes and Standards II establish and enforce written libit smoking in resident dicorridors. Smoking is	F99	999			
	1) The facility failed	d to provide adequate					

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) M A. BUII		PLE CONSTRUCTION G	(X3) DATE SURVEY COMPLETED	
		145662	B. WIN	G			
	ROVIDER OR SUPPLIER	ENTRE		83	EET ADDRESS, CITY, STATE, ZIP CODE 333 WEST GOLF ROAD IILES, IL 60714		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOULD I REFERENCED TO THE APPROPRIATE D	BE CROSS-	(X5) COMPLETION DATE
F9999	secured Dementia psychotic disorder through multiple so entries and in the crecord to be an unsisk. On 3-8-05 sor 6:38PM, R1 left the unit and exited the an adjoining unocc downstairs to the fi obtained cigarettes returned to 5 North 504), and closed the knowledge. R1 laid room 504 and lit a disintegrated the erinvolved the bed, he wall behind the R1 sustained 3rd d body resulting in ar lateral lower extrem multiple skin grafts ventilation, and a 3 as a direct result of the secured unit the alone on the unit (Edementia-type resident) assigned on the stairs on the first flot left the secured unit during the 3-8-the 5 South unit to	resident (R1) on the 5th floor unit with a diagnosis to include and who was identified cial service and nursing urrent care plan in the medical afe smoker and an elopement metime between 6:00PM and a 5 South secured Dementia 5th floor via the 5 North wing (upied unit) elevator, went rest floor smoking room, and a box of matches, entered and empty room (e door without staff down in the window bed of cigarette that started a fire that natire mattress. The fire also eadboards, privacy curtain, bed, and the bathroom door. egree burns to 25% of his extensive hospitalization, binities being amputated, intubation with mechanical 5% mortality rate of survival the fire. At the time R1 left ere was only one staff person (4), a nurse aide, with 33 dents picking up dinner trays. staff (E7-nurse and E5-nurse he secured unit and down for at dinner break when R1	F99	999			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) M A. BUI		PLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED	
		145662	B. WIN	IG		C 03/23/2005	
	ROVIDER OR SUPPLIER	ENTRE	•	83	EET ADDRESS, CITY, STATE, ZIP CODE 333 WEST GOLF ROAD ILES, IL 60714		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOULD I REFERENCED TO THE APPROPRIATE D	BE CROSS-	(X5) COMPLETION DATE
F9999	North Unit from din 3) The facility failed of 5 South (secured measures to preven unit without staff kn 4) The facility failed policy, stating that the security camera su	ner break. d to assure visitors' knowledge d unit) security and safety and residents from leaving the	F99	9999			
	services, facility's ir interviews, and writ staff: 1. Failed to follow the protocol (RACE). 2. Failed to evacua 3. Failed to contain the thick black smofloor Northwest cormild smoke inhalati unconscious in add burns to 25% of his hospitalization, bila amputation, skin gr Certified Nurse Aid emergency treatments.	rire safety procedures, in- ncident report dated 3/8/05, ten statements, the facility heir own fire procedure/ te R1 to a safe area. the fire in room 504 allowing ke to engulf the whole 5th ridor resulting in R1 sustaining on rendering R1 semi- lition to R1's third degree body which required teral lower extremities afts and intubation. E3 (e-C.N.A.) also required ent for smoke inhalation due to being contained to room 504.					
	The Findings includ	le:					

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:			(X2) M A. BUI		PLE CONSTRUCTION G	(X3) DATE SURVEY COMPLETED	
		145662	B. WING			C 3/2005	
	ROVIDER OR SUPPLIER	ENTRE		8	REET ADDRESS, CITY, STATE, ZIP CODE 333 WEST GOLF ROAD IILES, IL 60714	,	
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORREC (EACH CORRECTIVE ACTION SHOULD REFERENCED TO THE APPROPRIATE D	BE CROSS-	(X5) COMPLETION DATE
F9999	E7 (nurse) stated dinterview that on 3/4 there was a census South secured Den was the nurse on the and E5). 3/8/05 stated floor and went down dining room for bree 6:40PM. E7 also stated floor and went down dining room since staff dining room since staff dining room E4 and E5 both stated the staff dining room E4 and E5 both stated the staff dining room E4 and E5 both stated the staff dining room E4 and E5 both stated the staff dining room E4 and E5 both stated the staff dining room E4 and E5 both stated the staff dining room E4 and E5 both stated the staff dining room E4 and E5 both stated the staff dining room bread South unit. E4 stated that she observed E4 unit and approached where R1 was. Z5 the down to the 1st floot that he was right be waited for E5 to ret of R1 having left the returning. E4 then I go downstairs to the leaving E5 alone with residents. E5 stated the floor to look for E5 opened the fire North to investigate	uring a 3/11/05 telephone 8/05 on the afternoon shift of 33 residents on the 5 nentia unit. E7 stated that he hat unit with 2 nurse aides (E4 ffing schedule validated this at at 6:15PM he left the fifth extra that he saw E5 in the state that he saw E5 in the string at a nearby table with minutes after he arrived in m. Ited during 3/10/05 individual at on 3/8/05 E7 and E5 went k and left E4 alone on the 5 ed she was picking up dinner that R1 was missing and was on the 5 South unit. E4 said 25 and R2 returning on the d Z5 and asked if Z5 knew hold E4 that R1 had gone or with Z5 for a cigarette and whind her, but he was not. E4 urit to 5 South and notified E5 e unit with Z5 and not eff the 5 South secured unit to be first floor to look for R1, th 32 dementia type 5 South at that shortly after E4 left the 5 k1, E5 smelled smoke-like gh the exit doors from an	F99	999			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) M A. BUI		PLE CONSTRUCTION G	(X3) DATE SURVEY COMPLETED	
		145662	B. WIN	WING			3 /2005
	ROVIDER OR SUPPLIER	ENTRE	•	83	EET ADDRESS, CITY, STATE, ZIP CODE 333 WEST GOLF ROAD ILES, IL 60714		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOULD I REFERENCED TO THE APPROPRIATE D	BE CROSS-	(X5) COMPLETION DATE
F9999	room 504, with the protruding through the lower half still in pulled the fire alarm out of the room and fire. E5 stated that the flames on R1's to get a fire extinguing returned to extinguing the fire in room 504 immediately obtained North and joined Estin room 504, still leavithout any staff su statement notes the with fire extinguished windows in room 504 with fire extinguished windows in room 504 in the 5th floor and floor to the south st stated during 3/11/0 returned to 5 South minutes prior to E4 Facility failed to sup identified as high ris 8/05 sometime beto 1st floor smoking a matches accessible 11/05 telephone int 6 - 6:15PM while Z5 South secured unit cigarette, R1 approximations.	top half of R1's body the door into the hallway and in the room. E5 stated she in and came back to pull R1 I noticed R1's socks are on she used water to extinguish socks. E5 left R1 on the floor isher from 5 South and sh R1's feet and the room fire. North with R1 and the fire, the South were without any staff eriod of time. E4 returned to 5 hirs and observed E5 fighting i. E4 stated that she ed a fire extinguisher on 5 in her efforts to fight the fire eaving 5 South unit residents pervision. E4's 3/8/05 written at E4 assisted spraying the fire er, then proceeded to open 503, 502, 501, 529 and 528 fth floor via the north stairwell, walking through the fourth airwell up to 5 South unit. E7 05 phone interview, that he via the South stairway 2 returning to 5 South. Dervise 2 residents that are sk smokers (R1 and R2) on 3/ ween 6pm and 6:38PM in the rea with cigarettes and e to them. Z5 stated during 3/ erview that on 3/8/05 between 5 and R2 were exiting the 5 to go downstairs for a ached Z5 and asked to join and staff permission to leave the	F99	999			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) M A. BUI		PLE CONSTRUCTION G	(X3) DATE SURVEY COMPLETED	
		145662	B. WIN	G_			C 3/2005
	PROVIDER OR SUPPLIER	ENTRE	•	83	EET ADDRESS, CITY, STATE, ZIP CODE 333 WEST GOLF ROAD IILES, IL 60714		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORREC (EACH CORRECTIVE ACTION SHOULD REFERENCED TO THE APPROPRIATE D	BE CROSS-	(X5) COMPLETION DATE
F9999	South exit doors sa off the unit without during 3/11/05 photo by the 5 South exit a notice on the pan second delay. E4 s interview, that the 6 the 5 South exit do how to use the doo stated that R2 was unit from another unweeks prior to 3/8/0 E1 told surveyor that the 5 South secures stated that the only her about safety on residents see her puthe panel. Z5 stated the secured unit, or and down to the first R1 and R2 unsuper room, alone, while a desk, obtained a rerestroom and return desk. Z5 also stated cigarettes and a bos smoking area where and that upon return noticed her book of said that R1, R2 and elevator to the 5th fexited the elevator down corridor and inwhere Z5 was approand asked where R	there were no signs by the 5 ying not to take any resident staff knowledge. E5 stated ne interview that the only sign door that she remembers was ic bar of the door about the 15 tated during 3/11/05 phone only sign she remembered by or was one instructing visitors or code panel. E4 and E5 both admitted to 5 South secured nit in the facility a couple of	F99	999			

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		(X2) M A. BUI		IPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED		
		145662	B. WING			C 3/2005	
	ROVIDER OR SUPPLIER	ENTRE	ı	8	REET ADDRESS, CITY, STATE, ZIP CODE 333 WEST GOLF ROAD IILES, IL 60714		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORREC (EACH CORRECTIVE ACTION SHOULD REFERENCED TO THE APPROPRIATE D	BE CROSS-	(X5) COMPLETION DATE
F9999	Z5 turned around in Facility and fire depreports and staff int must have ducked and R2 were walking the elevator to the sclosed the room do and started smoking resident caught fire hands to pat out the burns on the hands that were still on fire R1's current care posupervised when so have independent a R1 has 13 docume cigarettes in unauth secured unit between R1's medical recordincidents of R1 gett unit without staff kn and once on 02/03/02/02/04 incident, if and was walking out a staff person driving R1. In addition, R1 home 8/18/03, a we this nursing home (facility to be at most surveillance, which floor nurses station	R1 was not there. Partment incident/ investigation rerviews revealed that R1 into room 504 when Z5, R1 ing down 5 North corridor from 5 South entrance doors, or, got into the window bed g a cigarette. The bed and R1 attempted to use his efire causing 1st degree and then removed his pants e. Ian stated that R1 is to be moking cigarettes and is not to access to smoking materials. Inted incidents of smoking incidents of south secured and 2/31/03 and 3/08/05. Indid documented 4 previous ing out of the 5 South secured incidence (twice on 02/01/04/04 and 02/29/04). During the R1 actually left the building into the parking lot, when ing into the parking lot noticed eloped from a prior nursing eek prior to being admitted to 8/25/03). R1 is identified by lerate risk for elopement.	F9:	999			
	On 3/10/05 surveyo	ors observed a security					

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		(X2) M A. BUI		PLE CONSTRUCTION G	(X3) DATE SURVEY COMPLETED		
		145662	B. WING			3/ 2005	
	ROVIDER OR SUPPLIER	ENTRE	l	8	REET ADDRESS, CITY, STATE, ZIP CODE 333 WEST GOLF ROAD IILES, IL 60714		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOULD I REFERENCED TO THE APPROPRIATE D	BE CROSS-	(X5) COMPLETION DATE
F9999	that is connected to floor nurses station president of operation of under 24 hour of because all resident are either independent supervised by a resident floor tour on 3/15/00 observed no facility station or in visual of the first floor lobby, door and the first floor lobby, door and the first floor and E1 observed to lobby, not the smoke monitors viewing sepushing a button at observed several resort of the first floor lobby, and the monitor viewing as pushing a button at observed several resort view that R1 stated that R1 stated that R1 stated that R1 has survival as a result	or corner of the smoking room of a 9 inch monitor at the 2nd of of that use the smoking room of the smokers or being of sponsible adult. During 2nd of at 2:10PM with E1, surveyor of staff in the 2nd floor nurses control of the monitor. This 2 utilizes 3 areas in the facility: the first floor side entrance for smoking room. Surveyor the monitor fixed on 1st floor of the monitor fixed on 1st floor of the smoking room by the which time the surveyor esidents using the smoking for. In did during 3/16/05 telephone of the smoking aright through the not right posterior thigh skin of a left below the knee of posterior thigh skin grafts on attention as a result of smoke multiple surgeries. Z4 also only a 35% mortality rate of of these burns.	F99	999			
	E4, E5) and written	nt report, staff interviews (E3, statements (E5, E6): On 3/8/ (CNA) discovers that R1 is					

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING			(X3) DATE SURVEY COMPLETED	
		145662	B. WING			3 /2005	
	ROVIDER OR SUPPLIER	ENTRE	ı	8	REET ADDRESS, CITY, STATE, ZIP CODE 333 WEST GOLF ROAD IILES, IL 60714		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOULD I REFERENCED TO THE APPROPRIATE D	BE CROSS-	(X5) COMPLETION DATE
F9999	on the floor (5 Sout due to E7 (Licensed CNA) being on breasignificant other) are asked them if they right behind them at there. E5 returns to R1 is missing. E4 at E4 leaves 5 South, passing room 504, for R1. As soon as hears E5 call for E4 through the fire docunoccupied unit) are with half his body in his body outside of lot of black smoke. fire alarm. Returns feet are on fire. E5 extinguish the flame on the floor to get of the south of the s	th. E4 is the only staff person h) with 32 dementia residents d Practical Nurse) and E5 (ak. E4 sees Z5 (R2's and R2 returning to 5 South and saw R1. Z5 states that R1 is and turns to see that he is not to 5 South and E4 tells E5 that and E5 continue to look for R1. With the fire doors to 5 North, to the elevator to go search the elevator doors shut, E4 d. E5 had also passed for from 5 South to 5 North (and observes R1 on the floor and observes R1 on the floor and observes R1 on the floor and observes R1 on the stated that she left to pull to pull R1 out of room but his stated to use water to es on R1's feet. E5 leaves R1 extinguisher. Toom 504, E4 observes E5 fer into room 504 while R1 out of the room. E4 runs and uisher to help E5. E4 says gR1 to move to the 5 North ch is directly across from as with extinguisher to help E5 was extinguishing the flames	F99	999			
	flames in the toilet is smoke was so thick breathe. E4 stated Northwest corridor	4 was extinguishing the room. E4 stated that the c and black it was hard to that she heads down the 5 to the stairwell (Northwest fire bunters E3 (CNA). E3, with					

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES (X1) PROVIDER/SUBBLIED/CLIA

-	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) M		IPLE CONSTRUCTION IG	(X3) DATE SURVEY COMPLETED	
		145662	B. WI	NG _		03/23	3/ 2005
	ROVIDER OR SUPPLIER	ENTRE		8	REET ADDRESS, CITY, STATE, ZIP CODE 3333 WEST GOLF ROAD NILES, IL 60714	03/20	3/2003
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOULD I REFERENCED TO THE APPROPRIATE D	BE CROSS-	(X5) COMPLETION DATE
F9999	fire extinguisher in entered the 5 North stairwell and stated station and R1 sittir. The door to room 5 black smoke in the Inside room 504, the sparking but no reaplace only one foot black smoke. E3 strin room 504 and ne extinguisher from the When E3 returned stated that he obsein front of room 504 as stated that he obsein front of room 504 as stated that R1 was kind of answer any question down the corridor to Stairwell and open yelling for help. As the firemen were the carried R1 down the lobby. Review of facility's C.E. is to be used. R is Rescue the page of the state of the page of the state	hand, stated he saw E4 as he livest corridor from the he saw E5 at the nurses' ag in a chair at nurses' station. O4 remained open with thick, corridor and room 504. Here was melting plastic with a liflames seen. E3 stated to into room due to the thick atted he used the extinguisher seded to get another the e5th floor Northwest corridor. With second extinguisher, E3 rived R1 on the corridor floor and did not see E4 nor E5. Ead they left the area. E3 stated unconscious and did not see E4 nor E5. Ead they left the area. E3 stated unconscious and did not see E3 stated unconscious and did not see E3 stated unconscious and did not see E3 and 2 other firemen e stairwell to the 1st floor. Fire procedure reflects that R.A R.A.C.E. is an acronym: attent.	F99	999			
	residents horizonta doors. Smoke door Notify supervisor of						

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) M A. BUI		IPLE CONSTRUCTION IG	(X3) DATE SURVEY COMPLETED		
		145662		B WING			C 3/2005
	ROVIDER OR SUPPLIER	ENTRE	'	8	REET ADDRESS, CITY, STATE, ZIP CODE 333 WEST GOLF ROAD IILES, IL 60714		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORREC (EACH CORRECTIVE ACTION SHOULD REFERENCED TO THE APPROPRIATE D	BE CROSS-	(X5) COMPLETION DATE
F9999	fire. Staff will close resident rooms. The facility's fire prodown into two more and persons on fire after the fire has be visitors evacuate from alarm. Obtain neare there are instruction extinguisher to extininstructions say new person. The other subcategors person is on fire, cond "pat" the fire out the person over, from the person over, from Review of fire safet shows that E6, E3, service. There was synopsis of what the linterview with E5 constated 3 different so has been in-service stated that she wou an extinguisher, sponder the pattinguish fire, and it to remove the patfire, and close door in the same constant of the pattinguish fire, and it to remove the patfire, and close door in the same constant of the pattinguish fire, and close door in the same constant of the pattinguish fire, and close door in the pattinguish fire, and it to remove the	all doors and windows to ceedure is further broken a categories, fighting the fire a. Fighting the fire reflects that the en discovered, residents and to me the area, and pull the fire est fire extinguisher then as on how to use the nguish the fire. The ver use direct contact on gory, persons on fire, states if over the person with blanket at. If no blanket available, roll om side to side, until fire is out. The very service dated 12/14/04 and E5 attended the inno explanation or brief in ein-service covered. The very service dated 12/14/04 and E5 attended the inno explanation or brief in ein-service covered. The very service dated 12/14/04 and E5 attended the inno explanation or brief in ein-service covered. The very service dated 12/14/04 and E5 attended the inno explanation or brief in ein-service covered. The very service dated 12/14/04 and E5 attended the inno explanation or brief in ein-service covered. The very service dated 12/14/04 and E5 attended the inno explanation or brief in ein-service covered.	F99	999			
	Surveyor asked E5	if room 504's door was left					

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES (X1) PROVIDER/SURPLIER/CLIA

AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 145662		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	A. BUI		IPLE CONSTRUCTION IG	(X3) DATE SU COMPLE	TED
		145662	B. WIN	IG _		C 03/23/2005	
NAME OF PROVIDER OR SUPPLIER GLEN BRIDGE N & REHAB CENTRE				8	REET ADDRESS, CITY, STATE, ZIP CODE 3333 WEST GOLF ROAD NILES, IL 60714	00/20	3/2000
(X4) ID PREFIX TAG	(EACH DEFICIENCY	ITEMENT OF DEFICIENCIES MUST BE PRECEEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOULD REFERENCED TO THE APPROPRIATE D	BE CROSS-	(X5) COMPLETION DATE
F9999	door to room 504 a showed up. Interview with E5 o phone stated wher she smelled smoke entering 5 North, E room 504 door ope leaves to pull the fir out and sees that F states that she use E5 states that she lextinguisher so she extinguisher so she extinguish R1's fee Interview with E4 o phone stated not to service she had att about the steps she was unable to say a linterview with E3 o phone stated to he who was working the residents on 4th floor upstairs via northworthwest Corridor 5th floor Northwest corridor at the north in a chair at the 5th along with E5. E3 s 504 is still open. E	stated that she closed the nd then the fire department in 3/10/05 at 4:15 p.m. via in she was searching for R1, and went to 5 North. Upon 5 saw R1 on the floor with in and smoke. E5 states she re alarm and returns to pull R1 R1's socks are on fire. E5 is water to extinguish the fire. It is water to extinguish the fire. It is can put out the fire and it. In 3/11/05 at 2:25 pm via or recall the last fire safety intended. When E4 was asked it should take during a fire, E4	F99	999			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) M A. BUI		PLE CONSTRUCTION G	(X3) DATE SU COMPLE		
	145662		B. WIN			C 03/23/2005		
NAME OF PROVIDER OR SUPPLIER GLEN BRIDGE N & REHAB CENTRE			1	83	EET ADDRESS, CITY, STATE, ZIP CODE 333 WEST GOLF ROAD IILES, IL 60714			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREF TAG		PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOULD I REFERENCED TO THE APPROPRIATE D	BE CROSS-	(X5) COMPLETION DATE	
F9999	Continued From page 32		F99	999				
	service he attended E4 stated to know the from fire, pull alarm asked if E3 closed who will he had closed the went to the was evaluated on 305 at night, E3 was went back to the horoom did chest x-ra and sent E3 home. the interview.	n was the last fire safety ind. E4 stated not to remember. o rescue the patient away, and close the door. When the door, E3 stated not to ed the door all the way. E3 ne hospital emergency room, s/8/05, and sent home. On 3/9/ still coughing. Therefore, E3 ospital and the emergency ys, an EKG, given aspirin, E3 stated to be okay during						
	via phone, E3 state fire extinguisher an which he obtained to corridor and upon he corridor floor in from E3 and E4. E3 state had left the area. Edown the 5th floor in the state of the st	d interview with E3 on 3/17/05 is that he used the 4th floor d needed another extinguisher from the 5th floor Northwest his return, E3 saw R1 on the at of room 504 and no sight of ed he assumed E3 and E4 is 3 stated that he dragged R1 northwest corridor to the where E3 was greeted by						
	17/05 via phone sta RN) informed E9 o was an alarm but it so E9 thought it wa went up the northw saw E4 opening the a lot of black smoke down to 4th floor ar	Registered Nurse - RN) on 3/ ated that the supervisor, E6 (if the fire. E9 stated that there only lasted for 2 to 3 seconds is just a test. E9 stated he est stairwell to 5th floor and door to stairwell. There was e. E9 instructed E4 to come and go up the other (southeast) South Unit along with E9. E9						

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) M A. BUI		PLE CONSTRUCTION	JRVEY TED	
		145662	B. WING			C 03/23/2005	
NAME OF PROVIDER OR SUPPLIER GLEN BRIDGE N & REHAB CENTRE				83	EET ADDRESS, CITY, STATE, ZIP CODE 333 WEST GOLF ROAD ILES, IL 60714	00,2	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFI TAG		PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOULD I REFERENCED TO THE APPROPRIATE D	BE CROSS-	(X5) COMPLETION DATE
F9999	and E4 enter 5 Sou Licensed Practical back to 2nd floor ar because he never h	ge 33 Ith and saw E5 and E7(Nurse). E9 stated he went a called a code red (fire) In eard any alarms. E9 stated the code red, E9 still never	F99	999			
	hear the fire alarm heard someone she floor. E6 attempted but due to the thick around and went up South. E6 stated he residents were okar	n 3/1105 at 3:45 p.m. stated to on 3/8/05 at 6:30 p.m. and outing there is a fire on 5th to go up northwest stairwell black smoke, E6 turned of the southeast stairwell to 5 e checked to see if 5 South by since E6 was the shift ed not to go into 5 North in were there.					
	finished his break a leaving the dining reheard the fire alarm stairwell (due to elewent to 5 South. E7 2 minutes before sehelped E7 assist 5 to the 1st floor lobb removed from the finand the door closed E7 stated to have a about a month ago, the alarm should be close the doors, rer	n 3/11/05 via phone stated he at 6:40 p.m. on 3/8/05 and was com/break room when he at E7 headed up the southeast evator was not working) and a stated he was on the unit for seeing E4. E7 stated that E4 South ambulatory Residents by Residents that could not be loor were left in their rooms distributed a fire safety in-service at E7 stated that during a fire, a pulled, confine the smoke, move residents, and with fire extinguisher.					

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING			(X3) DATE SURVEY COMPLETED	
		145662	B. WING			C 03/23/2005		
NAME OF PROVIDER OR SUPPLIER GLEN BRIDGE N & REHAB CENTRE				8	REET ADDRESS, CITY, STATE, ZIP CODE 333 WEST GOLF ROAD IILES, IL 60714	, 00/2	5/200	
(X4) ID PREFIX TAG			ID PREF TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS- REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE	
F9999	Continued From pa	ge 34	F99	999				
	failed to close the commoke and fire, failed area, and failed to extinguish flames of the station stated that to pm to 7 pm. The fire floor via stairwell. To smoke on 5th floor (himself and other fallway; it was E3 to stairwell. Z7 stated breathe due to the sift there were others the hall. Z7 stated to matter of feet due to stated that 2 fireme corridor and found R1 from the area. To from room 504 (hall and room 504). Z7 was open and the E were closed. Z7 siblack as the fireme firemen used a spet to tell which bed was mattress was burned mostly smoke. The	ireman) on 3/17/05 at the fire the call came in between 6:30 temen arrived and went to 5th there was a heavy white by fire exit. Z7 stated that they iremen) heard coughing in that the firemen pulled into the that it was very difficult to smoke. When E3 was asked on the floor, E3 pointed down that one could only see a to the thick white smoke. Z7 in went down the 5th floor R1. E3 was trying to remove they had gotten 2 rooms down frway between the stairwell stated that room 504's door Dementia Doors and fire doors tated that the smoke became in got closer to room 504. The cial thermal imagining device as on fire. Z7 stated that the ed up causing a few flames but the were no accelerants seen						
	not get hot enough Interview with Z11 of	did not go off because it did in the room. on 3/17/05 at the fire house arrived to the facility on 3/8/						

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) M A. BUII		PLE CONSTRUCTION	JRVEY TED	
		145662	B. WIN	G		C 03/23/2005	
NAME OF PROVIDER OR SUPPLIER GLEN BRIDGE N & REHAB CENTRE			•	83	EET ADDRESS, CITY, STATE, ZIP CODE 333 WEST GOLF ROAD ILES, IL 60714		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFI TAG	х	PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOULD I REFERENCED TO THE APPROPRIATE D	BE CROSS-	(X5) COMPLETION DATE
F9999	05, R1 was being be had pretty bad lower completely naked, a pain. Z11 stated that	prought down in a blanket and er extremity burns. R1 was alert and not complaining of at R1's legs were oozing blood oughing into a tear-drop	F99	999			
	stated that R1 com ambulance. R1 state of 1 to 10, 10 being given Advanced Lif bilateral lower (kne- second and third de	on 3/17/05 at the fire house plained of pain in the ted pain was a 10 on a scale the worst. Z12 stated R1 was e Support and morphine. R1's es down) extremities had egree burns but got worse had first degree burns to moke inhalation.					
	m. via phone stated extremity was ample posterior thigh skin 05, R1 underwent a left leg with a poste intubation resulted multiple surgeries.	Surgeon) on 3/16/05 at 2:45 p. If that R1's right lower utated at the knee with graft on 3/11/05 and on 3/15/a below the knee amputee on wrior thigh skin graft. The from the smoke inhalation and Z4 stated that R1 sustained a val rate as a result of these					
	a full basement. Th Type II (2,2,2) Prote consist of the follow * Exterior - Walls	ed in a five story building with e building construction type is ected - Non - Combustible and ving: are of 4" face brick with 8" lock backup and drywall					

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	, ,	MULTIPLE CONSTRUCTION (X3) DATE SU COMPLE ILDING				
	145662		B. WIN	IG		C 03/23/2005		
NAME OF PROVIDER OR SUPPLIER GLEN BRIDGE N & REHAB CENTRE			•	83	EET ADDRESS, CITY, STATE, ZIP CODE 333 WEST GOLF ROAD ILES, IL 60714			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFI TAG		PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOULD REFERENCED TO THE APPROPRIATE D	BE CROSS-	(X5) COMPLETION DATE	
F9999	interior finish. * Structure - All flethick pre-cast conceprotected steel beat * Corridors - All center of the study with 5/8" drywextending full heighted the system, and smoke smoke door and has system, and smoke smoke door and has buring the event of approximately 6:30 Procedures" were reflected by NFPA provision 19 Safety Code. The Procedures for all for ALARM, CONTAIN Activity during the tention focused on expression of the structure of th	oor slabs and roof deck are 8" rete slabs supported by ms and columns. corridors have 3 5/8" metal vall on both sides and at to the structure above. as an automatic sprinkler detectors in corridors, at azard areas. The fire on 3/8/05 at p.m., the facility "Fire Safety not followed as required in 7.1.1. 2000 Existing Life facility's Fire Safety ires reflects RACE - RESCUE, EXTINGUISH was not met. The fire event appears to have stringuishing the fire while the patient was not the priority overlooked and could have or closing the door to room 504	F99	999				