PRINTED: 03/10/2015 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION  A. BUILDING			(X3) DATE SURVEY COMPLETED	
145275		B. WING			C <b>03/05/2015</b>		
NAME OF P	ROVIDER OR SUPPLIER	110210	<u> </u>	STREET ADDRESS, CIT	TY, STATE, ZIP CODE	03/0	05/2015
				2220 STATE STREET			
TIMBERC	REEK REHAB & HEALTH	ICARE CENTER		PEKIN, IL 61554			
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	(EACH CC	DER'S PLAN OF CORRECTION DRRECTIVE ACTION SHOULD B FERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
F 000	INITIAL COMMENTS		FC	00			
F 323 SS=K	F323 cited Complaint Investigation deficiency cited. Complaint Investigation deficiency cited. Complaint Investigation deficiency cited. A partial extended surface and the su	ACCIDENT SION/DEVICES  ure that the resident as free of accident hazards	F3	23			
	by: Based on observation review the facility failed temperature of hallwad thermal hazard to ind This failure resulted in blister to the left elbout also failed to develop procedures following heaters no longer post These failures have the five residents (R1, R3)	ay heaters to prevent a ependently mobile residents. In R4 sustaining a burn with w on 1/13/15. The facility and implement policies and R4's burn to ensure hallway sed a thermal hazard. The potential to affect four of B, R4, R5) on the sample hazards and 94 residents					

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE (X6) DATE

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

Facility ID: IL6007330

COMPLETED
03/05/2015
E, ZIP CODE
AN OF CORRECTION (X5) VE ACTION SHOULD BE COMPLETION D TO THE APPROPRIATE DATE ICIENCY)
/ /

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION  (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  145275			(X2) MULTIPLE CONSTRUCTION A. BUILDING			(X3) DATE : COMPI	
		B. WING			C 03/05/2015		
NAME OF PROVIDER OR SUPPLIER  TIMBERCREEK REHAB & HEALTHCARE CENTER			,	STREET ADDRESS, CITY, STATE, ZI  2220 STATE STREET  PEKIN, IL 61554	IP CODE		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PROVIDER'S PLAN OF CORRECT PREFIX (EACH CORRECTIVE ACTION SHOLE TAG CROSS-REFERENCED TO THE APPRODE		ACTION SHOULD BE FO THE APPROPRIA		(X5) COMPLETION DATE
F 323 Continued From page 2		e 2	F3	323			
	"R4 found to have a during shower. Area with blister in the cer wheeling self in whe and laying R4's arm  On 3/03/15 at 8:45a person) used an infrathet emperatures of C-wing halls and the in front of a heater to then pointed the infraheater approximately which registered 141 verified the reading I hand, which felt neith measured the temperature of the word the temperature of the word the temperature of the word C206 which measured 141 continued of all the wall heater across from room C206 which measured 148 degrees to the men's resemble to the	m. E11 (Maintenance ared-thermometer to check the wall heaters in the four four B-wing halls. E11 stood cated next to room C105 ared-thermometer at the y two inches from the heater, I degrees Fahrenheit. E11 by feeling the wall with a bare her hot nor cold, then erature of the wall using the remained the wall heater, which remained heit. E11 measured the wall heater, which remained heit. E11 measured the wall heater located next to be easured 160-162 degrees afted, "That one seems pretty measuring the temperatures in the facility. The heater stroom on the B100 hall bees Fahrenheit. The heater heasured 173 degrees after next to room B106 bees Fahrenheit.					
	I -	n. E5 (Dietary Manager) librating a stem thermometer					

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA (X2) MULI IDENTIFICATION NUMBER:  A. BUILD		PLE CONSTRUCTION  G		(X3) DATE SURVEY COMPLETED	
		145275	B. WING			C 03/05/2015	
NAME OF PROVIDER OR SUPPLIER  TIMBERCREEK REHAB & HEALTHCARE CENTER				STREET ADDRESS, CITY, STATE, ZIP CODE 2220 STATE STREET PEKIN, IL 61554		3570572015	
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIES ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRE (EACH CORRECTIVE ACTION SH CROSS-REFERENCED TO THE APP DEFICIENCY)	IOULD BE	(X5) COMPLETION DATE	
F 323	the temperature real infrared-thermometer and all cup filled with ice ar E11 verified the digit degrees Fahrenheit 32 degrees Fahrenheit 32 degrees Fahrenheit.  The facility's Infrare manual dated 10/20 thermometers meas of an object To me unit at object and pure of an object and pure of an object and pure hallway heaters. The not blowing any hot stated E19, " usual about how E19 fixed to repair equipment documentation that temperature of the very on 3/03/15 at 6:30a wheelchair in the diremember that R4 rarm on the heater, "On 3/03/15 at 1:10p registers are warm,	and water in order to compare adings of the er. E11 placed the stem so a digital thermometer in a and a small amount of water. tal thermometer read 32.3 and, the stem thermometer read aneit and the er read 32 degrees  d-Thermometer instruction 202 states, "Infrared source the surface temperature easure a temperature, point call the trigger."  a.m. E11 stated that after R4 13/15, E11 and E19 tor), "checked all the C-wing may were all working properly, ter than suppose too." E11 and E19 did ." E11 was unable to provide E11 and E19 adjusted the wall heaters.  a.m. R4 was self-propelling a ming room. R4 was able to eceived a burn to R4's left	F 32	23			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION  (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:			(X2) MULTIPLE A. BUILDING	CONSTRUCTION	(X3) DATE SURVEY COMPLETED		
		145275	B. WING		C 03/05/2015		
NAME OF PROVIDER OR SUPPLIER  TIMBERCREEK REHAB & HEALTHCARE CENTER			2	TREET ADDRESS, CITY, STATE, ZIP CODE  220 STATE STREET  PEKIN, IL 61554	1 03.00.20.10		
(X4) ID PREFIX TAG	(EACH DEFICIE		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPI DEFICIENCY)	BE COMPLETION		
F 323	TAG REGULATORY OR LSC IDENTIFYING INFORMATION)		F 323				
	temping the heater documentation for temperature of the degrees or less."	facility was, "periodically s but there is no that." E1 stated, "The heaters should be 120 p.m. E2 (Director Of Nurses) tation that there were 98					

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION  (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  145275		` '	` '		_	(X3) DATE SURVEY COMPLETED
		B. WING_			C 03/05/2015	
NAME OF PROVIDER OR SUPPLIER				STREET ADDRESS, CITY,	STATE, ZIP CODE	03/05/2015
TIMBERCI	REEK REHAB & HEALT	HCARE CENTER		2220 STATE STREET PEKIN, IL 61554		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	(EACH CORF	R'S PLAN OF CORRECTION RECTIVE ACTION SHOULD BE RENCED TO THE APPROPRIA DEFICIENCY)	DATE
F 323	independently mobile the time of the survey.  An Immediate Jeopa approximately 1:40p. 1/13/15 when R4 sus elbow while leaning a hallway. E1 (Adminis Business Operations Immediate Jeopardy surveyor confirmed the	e residents in the facility at y.  Indy was identified at m. 3/04/15. It began on stained a burn to R4's left against a wall heater in the strator) and E15 (Director of ) were notified of the on 3/04/15 at 2:00p.m The prough interview and record	FS	223		
	The facility compleaters. They were until all temperatures degrees. (Complete degrees it would take second degree burn, safe temperature three	oleted a 100% audit of all wall continually adjusted were at or below 113 d: March 3, 2015) at 113 e two hours to develop a so it was decided that was a				
	place where all heate an infrared thermome or below 113 degrees 2015) A daily tracking submitted to the Adm discrepancies. The comaintenance Monday Saturday and Sunday be responsible for ten needs will be reporte Administrator. Additic conduct random tempappropriately.	ers will be tested daily using eter to ensure they remain at as. (Completed: March 3, g log will be maintained and sinistrator to monitor for daily temping will be done by through Friday and on y the weekend manager will mping them. Any emergent d to maintenance and the onally, the Administrator will perature audits and log ucted an in-service with staff heaters are only to be				

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		IDENTIFICATION AND ED		FIPLE CONSTRUCTION  NG		(X3) DATE SURVEY COMPLETED	
	145275 B. WING				C 03/05/2015		
NAME OF PROVIDER OR SUPPLIER  TIMBERCREEK REHAB & HEALTHCARE CENTER				STREET ADDRESS, CITY, STATE, ZIP ( 2220 STATE STREET PEKIN, IL 61554	CODE	03/03/2013	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFI TAG		TION SHOULD BE THE APPROPRIATE	(X5) COMPLETION DATE	
F 323	adjusted by the main was also educated to sitting in front of and Residents will be clost their rounds and through The in-service was conditionally adjusted to state the training Projected Completion All wall heater fabrick wall so that no adjust the temperature.	tenance department. Staff or redirect residents from for leaning on wall heaters. sely monitored by staff during aughout their daily activity. onducted by the and ADON. No employee rt their shift until they have 19. (Started: March 3, 2015;	F	323			